

### Setting

Photo Inventory

Outer Park Edges & Entry

The north side of the park is bordered by E. 6th. Native forest borders the remaining sides. Residential neighborhoods surround the park.

## Active Recreation Areas

Activite areas include:
Playground 5-12
Tot Lot
Pavement Games
Play Field

# Passive Recreation Areas

Benches Picnic Tables Picnic Shelter

### Playgrounds

7	Edaibilietir Elar		
N <sub>O</sub>	No. Item	Description	ssues/concerns
_	Big Toy Play Structure	ages 5-12, xx events,	Fair condition
	Structure	metal/wood, multiple play events	
2	2 2-bay Swing	2 belts and 2 tot seats	Fair to good condition
ω	Spring Toy	wood/metal	Good condition
4	4 Kompan Fire Truck wood/metal	wood/metal	Good condition
5	5 Play House/Slide	plastic/metal	Fair to good condition

Safety Surface

pea gravel

Good condition

Pathways Accessibility Overview
Equipment does not meet 50%%% requirement for ADA. Needs accessible swing element; play structure needs to be coordinated with manufacturer for ADA upgrades;

Concrete sidewalks on north perimeter. Ashpalt trail leads from playground. There are a number of dirt paths throught the forest E. 6th to

## Green Space

Open lawn areas.

## Location Map







**NE Park District** 

Ira Walker Park

& Analysis ....x ...x Inventory L1.0





1343 G Street, suite 101 Anchorage, Alaska 99501 (907) 279-2688 ehugglns@earthscape.alaska.com

earthscape

Municipality of Anchorage

Department of Parks and Recreation

Site