


East 6th Avenue

Review drainage along parking area, rework to provide positive drainage.

Install entry Type x with dog station and informational signs



Summary

Level 1 Improvements

- General maintenance
  - Remove graffiti
  - Repair lawn, add topsoil and seed.
  - Clean and repair picnic tables, shelter, trashcans.
  - Clean pea gravel from paved surfaces

Improve safety

- Review playground equipment for safety, alter as required
- Trim trees and undergrowth to improve sight lines
- Replenish safety surface at playground

Improve amenities

- Repaint hopscotch and four square
- Install new entry

Increase use opportunities


- Develop interpretive signs/exploration program in forest to encourage exploration, and provide educational opportunities.

Level 2 Improvements

Improve safety

- Review and repair pavement surface at 6th Avenue to make sure water is draining properly


date: 9/18/09
modified:



earthscape

1343 G Street, suite 101 Anchorage, Alaska 99501  
(907) 279-2688 ehuggins@earthscape.alaska.com

Department of Parks and Recreation

Municipality of Anchorage

Healthy Parks Healthy People

NE Park District

Ira Walker Park

Concept Design Ideas

L2.0 sheet X